690050

The JET JTM-1050 features Meehanite® castings, a heavy-duty hardened and ground 10" x 50" table, and high precision class 7 precision bearings support the spindle. Precision bored and honed milling heads ensure quality cuts, and the three-stage power downfeed with automatic stop makes the JET Variable Speed Milling Machines easy to use. JET precision engineering ensures superior results with all the features you've come to expect, all backed by the industry-leading JET Two Year Warranty

FEATURES

- · Certified Meehanite® Castings
- Hardened and ground table
- Chrome lead screws on X and Y axis
- Turcite B on X and Y axis
- · Satin chrome finish on dials
- Precision bored and honed milling head
- Large diameter quill is chromed
- High precision Class 7 spindle bearing
- Spindle head is internally cooled
- No fuse breaker power connections
- · Heavy duty motor drive
- Chrome plated motor shaft with bearing support at end
- One piece guill pinion and shaft
- Three stage power downfeed with automatic stop
- Heavy duty spindle break
- Locks on all moveable surfaces

- Hardened and ground square vertical knee ways and cross ways
- · Adjustable gibs throughout
- Internal coolant tank built into base for use with coolant system (coolant pump not included)
- Tolerance test sheet included
- One shot lubrication system
- Way covers
- Draw bar
- Tool box with tools





JET RED ASSURANCE 2-YEAR WARRANTY

JET warrants every product it sells. If one of our tools needs service or repair, one of our Authorized Service Centers located throughout the United States can give you quick service. In most cases, any of these JPW Industries Authorized Service Centers can authorize warranty repair, assist you in obtaining parts, or perform routine maintenance and major repair on your JET tools. For the name of an Authorized Service Center in your area call 1-800-274-6848

STAND BEHIND YOUR WORK™ JET



690050

SPECIFICATIONS

| Spindle Taper (In. x TPI) | R-8 |
|--|----------------------|
| Table Size (L x W) (In.) | 10 x 50 |
| Quill Diameter (In.) | 3-3/8 |
| Number of Spindle Speeds | Variable |
| Range of Spindle Speeds (RPM) | 70 - 3,800 |
| Quill Down Feed Rates (IPR) | .0015003006 |
| Spindle Travel (In.) | 5 |
| Head Movement (Deg.) | 90° R & L, 45° F & B |
| Max Distance Spindle to Table (In.) | 19 |
| Distance Spindle to Column (Max.) (In.) | 26 |
| Distance Spindle to Column (Min.) (In.) | 5-1/2 |
| Collet Capacity | 1/8 - 7/8 |
| Table Longitudinal Travel (In.) | 35 |
| Table Longitudinal Travel With Powerfeed (In.) | 29-3/4 |
| Table Cross Travel (In.) | 15-1/4 |
| T-Slots Number and Size (In.) | 3 and 5/8 |
| T-Slot Centers (In.) | 2-1/2 |





STAND BEHIND YOUR WORK™



690050

FULL SERIES

| STOCK NO | MODEL NO | DIGITAL READOUT | NUMBER OF AXIS | POWERFEED | POWER DRAW BAR | SPINDLE TAPER (IN. X TPI) |
|----------|----------|-----------------|----------------|------------------|----------------|---------------------------|
| 690050 | JTM-1050 | | | | | R-8 |
| 690120 | JTM-1050 | | | X-Axis | | R-8 |
| 690150 | JTM-1050 | | | X and Y-Axis | | R-8 |
| 690450 | JTM-1050 | ACU-RITE 203 | | X, Y and Z-Axis | | R-8 |
| 690117 | JTM-1050 | ACU-RITE 200S | 2 | X-Axis | | R-8 |
| 690216 | JTM-1050 | ACU-RITE 200S | 2 | X-Axis | | |
| 690235 | JTM-1050 | ACU-RITE 200S | 2 | X-Axis | Pneumatic | R-8 |
| 690214 | JTM-1050 | ACU-RITE 200S | 2 | X and Y-Axis | | R-8 |
| 690258 | JTM-1050 | ACU-RITE 200S | 2 | X, Y and Z-Axis | Pneumatic | R-8 |
| 690158 | JTM-1050 | ACU-RITE 200S | 3 (Quill) | X-Axis | | R-8 |
| 690159 | JTM-1050 | ACU-RITE 200S | 3 (Quill) | X and Y-Axis | | R-8 |
| 690151 | JTM-1050 | ACU-RITE 200S | 3 (Quill) | X and Y-Axis | Pneumatic | R-8 |
| 690160 | JTM-1050 | ACU-RITE 200S | 3 (Quill) | X, Y, and Z-Axis | | R-8 |
| 690164 | JTM-1050 | ACU-RITE 203 | 3 (Knee) | X-Axis | | R-8 |
| 690256 | JTM-1050 | ACU-RITE 203 | 3 (Knee) | X and Y-Axis | | R-8 |
| 690306 | JTM-1050 | ACU-RITE 303 | 2 | X-Axis | | R-8 |
| 690307 | JTM-1050 | ACU-RITE 303 | 2 | X and Y-Axis | | R-8 |
| 691204 | JTM-1050 | Newall DP700 | 2 | | | R-8 |
| 691172 | JTM-1050 | Newall DP700 | 2 | | Pneumatic | R-8 |
| 691205 | JTM-1050 | Newall DP700 | 2 | X-Axis | | R-8 |
| 691206 | JTM-1050 | Newall DP700 | 2 | X and Y-Axis | | R-8 |
| 691207 | JTM-1050 | Newall DP700 | 3 (Quill) | | | R-8 |



STAND BEHIND YOUR WORK™



690050

FULL SERIES

| STOCK NO | MODEL NO | DIGITAL READOUT | NUMBER OF AXIS | POWERFEED | POWER DRAW BAR | SPINDLE TAPER (IN. X TPI) |
|----------|----------|-----------------|----------------|--------------|----------------|---------------------------|
| 691209 | JTM-1050 | Newall DP700 | 3 (Quill) | X and Y-Axis | | R-8 |
| 690234 | JTM-1050 | Newall DP700 | 3 (Quill) | X, Y, Z-Axis | Pneumatic | R-8 |
| 691234 | JTM-1050 | Newall DP700 | 3 (Knee) | | | R-8 |
| 691236 | JTM-1050 | Newall DP700 | 3 (Knee) | X-Axis | | R-8 |



STAND BEHIND YOUR WORK™ JET

